

Summary ECM Control Report

Existing Switch	Proposed Control	Switch Qty	Control Qty
		Ex	Pro
Dual Gang	Dual Gang Wall Sensor	244	244
None	None	1	0
Single Gang	Single Gang Wall Sensor	36	36
Dimmer	Existing	3	0
On Fixture	None	474	0
DT Sensor	Existing	34	1
Timer	Existing	23	0
Four Gang	Ceiling Sensor	13	13
Dual Gang	Hibay Sensor	1	40
None	Hibay Sensor	0	19
Totals		829	353